

## ANEXO A: REPORTAXE FOTOGRÁFICA

Foto 1 - Vista da fachada norte do edificio



Foto 2 - Vista da fachada este do edificio



**Foto 3 - Vista da fachada sur do edificio**



**Foto 4 - Vista da fachada oeste do edificio**



**Foto 5 - Vista da entrada principal ao edificio**



**Foto 6 - Vista da cuberta do edificio (I)**



**Foto 7 - Vista da cuberta do edificio (II)**



**Foto 8 - Vista da cuberta do edificio (III)**



**Foto 9 - Vista do interior do edificio (I)**



**Foto 10 - Vista do interior do edificio (II)**




Foto 11 - Vista do interior do edificio (III)



Foto 12 - Vista do interior do edificio (IV)

